Declassified in Part - Sanitized Copy Approved for Release 2012/04/11 : CIA-RDP78-03424A000500120006-9

## Office Memorandum • UNITED STATES GOVERNMENT

To : The Files

DATE: 3 May 1957


FROM :

Lle RD-79 T.O. 7

25X1

SUBJECT: (E/CS-3() Input Power Cables and Recorder TB E-701, ED-71)

- 1. Input power cables from the aircraft/switch/fuse indicator box to the input of the rack filter as fabricated under RD-79, T.O. VII, have been fabricated of #20 wire on the basis of the wire size contained in the original cable (W-1205).
  - a. The use of this size wire under the maximum length installation conditions will result in about a 4-volt drop in the 28 volt supply. This is considered as resulting in marginal operating voltages, except when the actual length used is under 5-feet.
  - b. The contractor has been requested to replace these cables with #14 wire size. Two each of these cables "28VDC INPUT #1 ....9" now in stock are being requisitioned back to the contractor for replacement.
  - c. This change will require the contractor to procure the following additional material:
    - (1) 4650 ft., 2 conductor #14 stranded, shielded cable,
      - (2) 93 replacement connectors.
  - d. Contractor will re-utilize the presently prepared sleeving and cable markers.
    - e. No change in stock numbers are involved.
  - 2. Internal Recorder Wiring change:
  - a. Cable arrangements for the E/CS-3() configurations have been largely based upon the examination of Figure 1-13, Figure 4-1, and physical check out of cable assemblies W-1203, W-1202, and W-1205. Early check out established that when 28 vdc was applied to recorder receptacle J-702 pins A and B that recorder motors and internal oscillator filaments were in an operative condition.



CONFIDENTIAL

- b. The two recorder units furnished the contractor have been previously established as having a different receptacle configuration, in that a provision has been made for a cable plug retainer feature.
- c. However, when voltage was applied to J-702 pins A and B of these recorders it was found that the motor circuits were not completed. Examination indicated that Recorder Terminal Board 701, as contained in Figure 1-13, had been re-arranged so that the positive bus contained in this figure is now in two segments. Comparison with a random selected recorder indicated that this condition was also true. A check with of T&I Section established that the field has encountered both the TB as reported above and the TB as shown in Figure 1-13. indicated that the two section boards were strapped in the field for his applications.

25X1

25X1

3. It is considered necessary that each recorder used with the E/CS-3 configuration have its terminal board strapped to conform with Figure 1-13.

25X1

CONFIDENTIAL